

Touring Tips & Maintenance Techniques

Provided by Colin Gurnsey

Engine Turn: Turning the engine to assist in adjusting valve clearances or contact breaker points is often awkward, unless the crankshaft pulley nut is easy to get to. An easier way is to jack up one rear wheel, put the car in top gear and turn the wheel to rotate the engine. Not a good idea with later cars with a posi -trac rear-end though.

Truer Gasket Holes: I used to have difficulty always getting the hole punch to perfectly rim the lines I'd

drawn for a new gasket hole. One time when I went to pick up a head gasket made for me by a local gasket maker I enquired how he got the holes so true. He showed me a template in cardboard he had made up that had the key hole sizes he was using. He laid the template over the drawn circle to be punched. He then hole punched the hole with the template as a guide. My gasket holes now turn out perfect every time.

New Members

Ron Wade & Susie Conley 1605 NE 112th St Vancouver, WA 98686 smcttc@gmail.com

360-606-1429 (C); 360-816-0216 (B)

Chad & Billie Shoemaker

8105 Chehalis Rd Blaine, WA 98230 chadshoemaker@msn.com 360-371-0210 (H); 360-318-0210 (B) Kenneth Krolikoski

14252 SW Mistletoe Drive Tigard, OR 97223 Kenk@tbirdman.com 503-579-1086 (H); 917-219-0554 (B) 1932 Packard 8, 903, Coupe Roadster

Member Changes:

Carl & Chris Bomstead 760-469-2275 (CA)

Bill & Karel Deibel karelorbill@gmail.com

Linda Ellison

llellison@ mac.com

Robert & Leesa Justice

1934 Packard Std 8, Dual Windshield Phaeton

Jon Schoenfeld

jonmschoenfeld@gmail.com

Gerald Schimke 4622 SW Myrtle St, Seattle, WA 98136-1754

James Warjone PO Box 4570, Ketchum, Idaho, 83340



INSURING YOUR VEHICLES FOR OVER 50 YEARS

UNPARALLELED CLAIMS SERVICE
AGREED VALUE COVERAGE
EXCELLENT CUSTOMER SERVICE

